# **Forest View Acres Water District**

Operations Report - February 2020

Prepared by Clyde Penn ORC Water Professionals

# **Arapahoe Water Plant**

- The plant produced 100% of demand for August
- Purged Chlorine Analyzer as Needed
- Plant Checks, Mixed Chemicals
- Replaced Faulty Solenoid Valve on CL17 Supply Line
- Rebuilt Valve on Filter #3 Leaking out of Weep Hole

# **Booster Pump Station**

- Checked Booster Station
  - IT showed up and updated program so that alarms are more easily cleared once alarm is taken care of. Found on the old program that alarms could not be cleared

#### Distribution

- Meters were Read on 27 January 2020
- Service Line leak at 4825 Limestone (Repair Est Included) This is the second time this service line has leaked within a couple of years. Last time line was patched Recommend replacement of this line
- Monthly BACTI's
  - HAA5/TTHM Samples taken
  - Upcoming samples include SOC/VOC, Fluorides

### **Surface Water Plant**

- The plant produced 0% of demand for November because of low water flow in the canyon inlet pressure is at about 20 psi Still getting water out of the pipe, just no pressure
- Completed monthly MOR report for state No Violations Plant offline
  - Going to have a New MOR Report that will need to be filled out once plant is back online

### **Locates**

- New Company doing locates - Haven't been contacted by them for any help

# Production for the Month of January 2019

Year	Month	SWTP Production - BW	% of Total	AWP Production	% of Total	Total Production	Total Water Sold	Percentage Discrepancy
	Jan	0	0%	1,680,427	100%	1,680,427	1,277,263	23.99%
	Feb	0	0%	1,335,096	100%	1,335,096	1,031,991	22.70%
	Mar	0	0%	1,533,895	100%	1,533,895	1,183,118	22.87%
	Apr	-63,912	-4%	1,748,857	104%	1,684,945	1,183,142	29.78%
	May	-35,803	-2%	1,867,532	102%	1,831,729	1,398,912	23.63%
2019	Jun	183,124	9%	2,005,631	92%	2,188,755	1,732,721	20.84%
2019	Jul	1,009,434	42%	1,408,667	58%	2,418,101	1,842,689	23.80%
	Aug	-710	0%	2,494,354	100%	2,493,644	1,909,733	23.42%
	Sep	-67,885	0%	2,766,096	103%	2,698,211	2,082,272	22.83%
	Oct	0	0%	2,199,877	100%	2,199,877	1,416,580	35.61%
	Nov	0	0%	2,379,072	100%	2,379,072	1,223,100	48.59%
	Dec	0	0%	1,300,350	100%	1,300,350	1,167,076	10.25%
Total		1,024,248	4%	22,719,854	97%	23,744,102	17,448,597	26.51%
		SWTP						
Year	Month	Production - BW	% of Total	AWP Production	% of Total	Total Production	Total Water Sold	Percentage Discrepancy
Year	Month Jan	Production -	% of Total	AWP Production 2,061,922	% of Total			_
Year		Production - BW				Production	Sold	Discrepancy
Year	Jan	Production - BW				Production	Sold	Discrepancy
Year	Jan Feb	Production - BW				Production	Sold	Discrepancy
Year	Jan Feb Mar	Production - BW				Production	Sold	Discrepancy
	Jan Feb Mar Apr	Production - BW				Production	Sold	Discrepancy
Year 2020	Jan Feb Mar Apr May	Production - BW				Production	Sold	Discrepancy
	Jan Feb Mar Apr May Jun	Production - BW				Production	Sold	Discrepancy
	Jan Feb Mar Apr May Jun Jul	Production - BW				Production	Sold	Discrepancy
	Jan Feb Mar Apr May Jun Jul Aug	Production - BW				Production	Sold	Discrepancy
	Jan Feb Mar Apr May Jun Jul Aug Sep	Production - BW				Production	Sold	Discrepancy
	Jan Feb Mar Apr May Jun Jul Aug Sep Oct	Production - BW				Production	Sold	Discrepancy

SWTP Offline JAN/FEB/MAR 2019 because of Frozen Supply Line
SWTP Offline SEPT/OCT/NOV 2019 because of low flow in the Canyon
Flushed Hydrants on Rockbrook Dr because of water quality complaint – Brown Water.
2" Main on Clovenhoof was flushed multiple times during sewer line installation
SWTP Offline – Low Water Flow in Canyon; No pressure on line

Flushed Hydrants Multiply times during the work on Forest View Rd

### 2018 Water Leaks:

- 11 February 2018 Forest View and Red Forest: Repaired by J&K; Flowed Hydrants after Repairs
- 27 August 2018 Sandstone and Pixie Park PRV Leaking; Parts (SS) on order Setting up a date for Repair/Training to install parts
- 27 August 2018 4315 Sandstone service line leak Isolated/Repaired
- 29 October 2018 Sandstone and Pixie Park PRV Leaking at outlet pressure gauge Repaired
- 08 December 2018 Main Leak Red Forest Rd. Repaired by Global
- 23 December 2018 Service Line Leak 3765 Sierra Vista Repaired by Homeowner

### **2019 Water Leaks:**

- 13 March 2019 Service Line Leak 3830 Range View Being repaired by homeowner
- 05 June 2019 Main Line Break on Oxbridge Hit by Foothills Electric
- 23 October Service Line Break on Rockbrook Dr. Repaired by Homeowner
- Flushed Hydrants on Rockbrook Dr because of water quality complaint Brown Water.
- 2" Main on Clovenhoof was flushed multiple times during sewer line installation

## **Meters**

Total of 326 Meters in District of which 325 are Remote Reading currently

### 2019 New Meter Installations / Water Taps:

4660 Red Stone Ridge Rd

4640 Red Stone Ridge Rd

Two meters installed for new homes on Forest View Rd.

Date:

February 13, 2020

Attn:

Clyde Penn

Forest View Acres Water District

Phone: 719-200-8184 cpenn@orcwater.com

Re:

Budget to replace water service line from corp stop to curb stop (up to 75 LF) - Revised with no asphalt 2-13-2020

4825 Limestone Road Global Underground Corp

			Propos	ed Contr	act Markups	\$5,769.04
General markup: 10% of Permits & Dump Fees						\$250.00
Subcontractor markup: 10% of subcontractors						\$318.00
Equipment Markup: 10% of equipment						\$451.14
Materials Markup: 10% of materials						\$213.50
Labor Burden: 35% of labor						\$1,317.99
Overhead: 10% of Project Direct Costs						\$1,609.21
Profit Margin: 10% of Project Direct Costs						\$1,609.21
Contract Markups						
			Estimated Project Direct Cost		Direct Costs	\$16,092.08
General - EPCO Permit	1	LS	2,500.00			\$2,500.00
Subcontractor - Density Testing	4	EA	90.00			\$360.00
Subcontractor - Traffic Control	1	LS	900.00			\$900.00
Subcontractor - Tandem Trucking (Haul of sand and base & haul off of dirt)	24	HR	80.00			\$1,920.00
Materials - Seed and Blanket (approx. 1200 SF)	1	LS	675.00			\$675.00
Materials - CL6 Road Base / Gravel to Repair Road (Approx. 1 Load)	1	LS	225,00			\$225.00
Materials - 3/4" Copper and curb stop with box	1	LS	675.00			\$675.00
Materials - Sand Bedding (Approx. 2 Loads)	1	LS	560.00			\$560.00
Equipment - Semi Truck with Trailer (Moves)				4	87.00	\$348,00
Equipment - Trench Shoring				24	20.60	\$494.40
Equipment - Skid Steer				24	37.00	\$888.00
Equipment - Mini Excavator (Rental)				24	75.00	\$1,800.00
Equipment - Connex Tool Trailer				24	15.00	\$360.00
Equipment - Crew Truck				24	17.25	\$414.00
Equipment - Crew Truck				12	17.25	\$207.00
Labor - Move Truck Driver Crew				4	32.96	5131.84
Labor - Laborer - General				24	23.69	\$568.56
Labor - Laborer - Lead				24	27.81	\$667.44
Labor - Operator				24	32.96	5791.04
Labor - Foreman				24	41.20	\$988.80
Description Labor - Superintendent (1/2 Time)	260	antity	Unit Price	Hours 12	Hourly Rate 51.50	Total Price \$618.00

**Total Budget Price** 

\$21,861.12

C	ar	lfi	ica	ti	on	15

Hydro Vac / Potholing work is excluded

Assumes no conflicting utilities exist in proximity of the work that would cause delays

Bond is Excluded